

## K76313281: The BIG-IP system may advertise unsupported SHA algorithms erroneously when performing certificate authentication with the TLSv1.2 protocol

### Known Issue

**Original Publication Date:** Oct 31, 2016

**Update Date:** Mar 14, 2017

### Known Issue

The BIG-IP system may advertise unsupported SHA algorithms erroneously when performing certificate authentication with the TLSv1.2 protocol.

This issue occurs when all of the following conditions are met:

- You have a virtual server configured with a Client SSL profile on the BIG-IP system.
- The Client SSL profile has the client certification authentication set to **Request** or **Required**.
- The client attempts to select one of the following unsupported signature algorithms advertised by the BIG-IP system during the Secure Sockets Layer (SSL) handshake process:
  - SHA256-RSA
  - SHA384-RSA
  - SHA512-RSA

### Impact

The BIG-IP system may erroneously allow the client to select an unsupported signature algorithm when performing certificate authentication. As a result, the client fails to connect to the virtual server.

### Symptoms

As a result of this issue, you may encounter one or more of the following symptoms:

- [BIG-IP iHealth](#) lists Heuristic H617888 on the **Diagnostics > Identified > Medium** screen.
- When SSL debugging is turned on, an error message similar to the following example appears in the `/var/log/ltn` log file:

```
debug tmm3[1234]: 01260009:7: Connection error: ssl_hs_rxhello:4489: unsupported version (70)
```

- The network packet capture shows the failed client connection uses the following signature algorithms during the SSL handshake process:
  - SHA256-RSA (0x0401)
  - SHA384-RSA (0x0501)
  - SHA512-RSA (0x0601)

- The network packet capture shows the successful client connection uses the SHA1-RSA (0x0201) signature algorithm during the SSL handshake process.

## Resolution

### Status

F5 Product Development has assigned ID 451003 to this issue. F5 has confirmed that this issue exists in the products listed in the **Applies To** box, located in the upper-right corner of this article. For information about releases or hotfixes that resolve this issue, refer to the following table:

Type of Fix	Fixes Introduced In	Related Articles
Release	11.5.0	<a href="#">K2200: Most recent versions of F5 software</a>
Hotfix	11.4.1 HF9 11.2.1 HF16	<a href="#">K9502: BIG-IP hotfix matrix</a>

### Workaround

None

### Supplemental Information

- [K4918: Overview of the F5 critical issue hotfix policy](#)
- [K167: Downloading software and firmware from F5](#)
- [K17465: Determining if a Known Issue is resolved for a specific BIG-IP version](#)
- [K13123: Managing BIG-IP product hotfixes \(11.x - 12.x\)](#)
- [K14819: Troubleshooting client certificate authentication](#)
- [K5532: Configuring the level of information logged for TMM-specific events](#)
- [K14783: Overview of the Client SSL profile \(11.x - 12.x\)](#)

Applies to:

**Product:** BIG-IP, BIG-IP LTM  
11.4.1, 11.4.0, 11.3.0, 11.2.1